FIG. 1





FIG. 2



3 / 12

## FIG. 3

$$H = \begin{pmatrix} R(1,1) & \cdots & R(1,K) \\ \cdots & \cdots & \cdots \\ R(J,1) & \cdots & R(J,K) \end{pmatrix}$$

$$R(j,k) = Q(j,k) \otimes P(j,k)$$

FIG. 4




FIG. 5




FIG. 6





FIG. 7



8 / 12

FIG. 8




FIG. 9A

FIG. 9B

FIG. 9C 
$$H = (R(j,k)) = (Q(j,k) \otimes P(j,k)) = \begin{cases} 001000|000100|010000|\\ 010000|00001|0001000|\\ 100000|00001|100000|00001|\\ 000010|001000|001000|\\ 000010|100000|000100|\\ 000100|00100|00100|\\ 000100|000001|00000|\\ 001000|00001|00000|\\ 001000|00001|00000|\\ 010000|0001|00000|\\ 010000|0001|00000| \end{cases} 903$$

9/12





FIG. 11

c (1)	c (2)	c (3)	c (4)	r + c (1) + c (2) +c (3) + c (4)
-------	-------	-------	-------	-------------------------------------

FIG. 12



11 / 12


FIG. 13

## FIG. 14A PRIOR ART

$$H = \begin{pmatrix} 1 & 2 & 3 & 4 & 5 & 6 & 7 & 8 \\ 1 & 0 & 0 & 1 & 0 & 1 & 1 & 1 \\ 0 & 1 & 1 & 1 & 0 & 1 & 0 & 1 \\ 1 & 1 & 0 & 1 & 1 & 1 & 0 & 0 \\ 1 & 0 & 1 & 0 & 1 & 0 & 1 & 1 \end{pmatrix} \begin{pmatrix} 1 & 2 & 3 & 3 & 3 \\ 3 & 4 & 3 & 3 & 4 & 3 \end{pmatrix}$$

PARITY CHECK MATRIX H

FIG. 14B PRIOR ART



TANNER GRAPH G

FIG. 15 PRIOR ART

